

A5

location; decrementing the toner level register for the print engine at the printing location if the accumulated value is less than or equal to the toner level of the print engine; and sending the print job to the print engine at the printing location for rendering.--

REMARKS

Please charge any additional fees or deficiencies in fees or credit any overpayment to Deposit Account No. 20-0780/TRSY-25,474 of HOWISON, CHAUZA, THOMA, HANDLEY & ARNOTT, L.L.P.

Respectfully submitted,

HOWISON, SHAUZA, THOMA, HANDLEY & ARNOTT, L.L.P.

Attorneys for Applicants

Gregory M. Howison

Registration No. 30,646

GMH/jk P.O. Box 741715 Dallas, Texas 75374-1715 972/479-0462 March 13, 2001